RIC 2003

Building on the Davis-Besse Experience Session T1

NRC's Davis-Besse Task Force

Cindi Carpenter, Chief
Inspection Program Branch
Division of Inspection Program Management
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission

April 17, 2003





Background

- Davis-Besse Task Force Report issued Sept 30, 2002, contained 51 recommendations to improve regulatory process
- Stakeholders believe that ROP was not effective in identifying vessel head degradation
- Improvements to NRC Inspection Program



Major Themes for NRC Inspection Program

- Need to better integrate inspection program and operating experience
- Need to direct inspectors into areas of known generic concerns and provide periodic inspector training on current technical issues
- Need to follow up on licensee responses to generic communications
- Need to maintain a questioning attitude
- Communicate expectations for inspector follow up



Several Recommendations Pointed Towards Need to Enhance NRC Inspection of Corrective Action Programs

- Licensee corrective actions associated with industry operating experience
- Licensee actions associated with NRC generic communications
- Licensee corrective actions for longstanding/repetitive problems
- Deferred modifications or deferred corrective actions
- Assess production influences on outage work scope.



Specific Activities in Response to Lessons Learned Recommendations

- NRC senior management review team prioritized high priority recommendations and categorized into 4 groups:
 - Assessment of stress corrosion cracking
 - Assessment and Integration of Operating Experience
 - Evaluation of Inspection, Assessment, and Project Management Guidance
 - Assessment of Barrier Integrity Requirements
- Remaining recommendations integrated into operational planning activities

USNRC RIC, April 2003 5



Assessment of Stress Corrosion Cracking

- Evaluate development of improved inspection guidance for RPV head and VHP nozzles
 - Establish technical basis for new inspection guidance
- Evaluate current BACC programs and whether additional inspection guidance or regulatory requirements are necessary
- Ensure NRC inspection guidance provides effective oversight of licensee RPV head inspections and BACC programs

USNRC RIC, April 2003 6



Assessment and Integration of Operating Experience

- Formed inter-Office operating experience task group
- Identify Agency needs and objectives in operating experience and changes necessary
 - Need to better integrate inspection program and operating experience in the short and long term
 - Need to direct inspectors into areas of known generic concerns



Inspection, Assessment, and Project Management Guidance

- Ensure sufficient inspections are conducted of:
 - Long-standing, unresolved problems that don't progress to a finding
 - Corrective actions phased over several years or Refueling Outages
 - Deferred modifications or deferred corrective actions.
 - Enhance guidance to pursue issues and problems identified during inspector plant status reviews
 - Reinforce expectation for maintaining a questioning attitude
- Management of organization and resources for plants in extended shutdown

USNRC RIC, April 2003 8



Assessment of Barrier Integrity Requirements

- Review and improve leakage detection requirements and inspection guidance
- Perform comprehensive review and evaluation of plant experiences, current leakage detections systems, and state-of-the-art systems
- Review and improve barrier integrity performance indicators:
 - Improve existing BI PI based on current requirements and measurements
 - Evaluate feasibility of an additional BI PI to track number, duration, and rate of primary system leaks
 - Evaluate feasibility of establishing a risk-informed BI PI
- Need to look at inter-relationships between regulations, Pls, & inspection guidance